Acetone

Part # - 9

The Industry Standard in Cleaning
#9 is the standard of the industry for cleaning tools and brushes while working in polyester, vinyl ester, and epoxy resins. It is also the recommended solvent for removing greases and waxes from surfaces which are to be bonded, repaired or primed. It is not recommended for thinning resins or gel coats as this can lead to added pinholes and premature yellowing. Handle with the same care reserved for gasoline.

Product Specifications

Specs	Mass%	Method	Limits
Purity	Mass%	G.C.	Min. 99.5
Water	Mass%	ASTM D-1364	Max. 0.5
Acidity (as acetic acid)	Mass%	ASTM D-1613	Max. 0.002
Alkalinity (asNH3)	Mass%	ASTM D-1614	Max. 0.001
Color	Pt/Co	ASTM D-1209	Max.5
S/G @ 20/20 deg.C		ASTM D-4052	0.7910-0.7930
Permanganate Stability	Min. @ 25C	ASTM 1363	Min. 120
Non-Volatile Matter	Mg/100ml	ASTM 1722	Max 2
Benzene	Mg/kg	GC	Max 10
Appearance		ASTM D-3741B	*CFFMS

*CFFMS – Clear & Free of Suspended Matter

Storage

Keep out of Reach of Children. Extremely Flammable. All containers should be properly labeled to prevent accidental ingestion or improper disposal. Individuals should reseal any partly used material back in the container. Store under cool, dry conditions away from open flames and high temperatures. For more detailed instructions on storage, please see the MSDS Sheet.

Safety and Handling

#9 Acetone contains ingredients that could be harmful if mishandled. Contact with skin and eyes should be avoided and necessary protective equipment and clothing should be worn. Individuals should wash with soap and water before eating, drinking, or using toilet facilities. Individuals should observe conditions of good industrial hygiene and safe working practices. For more detailed instructions on handling please refer to the MSDS Sheet.

Information present herein has been compiled from sources considered to be dependable and is accurate and reliable to the best of our knowledge and belief but is not guaranteed to be so. Nothing herein is to be construed as recommending any practice or any product violation of any patent or in violation of any law or regulation. It is the user's responsibility to determine for himself the suitability of any material for a specific purpose and to adopt such safety precautions as may be necessary. We make no warranty as to the results to be obtained in using any material and, since conditions of use are not under our control, we must necessarily disclaim all liability with respect to the use of any material supplied by us.
©Copyright 2010 Fibre Glast Developments Corporation

Fibre Glast Developments Corporation
385 Carr Drive
Brookville, Ohio 45309
Phone – 800.214.8579
Fax – 937.833.6555
www.fibreglast.com