



FIBRE GLAST DEVELOPMENTS CORP.  
385 CARR DRIVE  
BROOKVILLE, OH 45309  
REV 06/07

TELEPHONE: (937) 833-5200  
FAX: (937) 833-6555  
**FOR CHEMICAL EMERGENCY  
CALL (800) 424-9300 24 HRS.**

---

## SECTION 1 – PRODUCT IDENTIFICATION

---

**PRODUCT NAME:** PART #1063 Kevlar

**IDENTITY:** Para Aramid Nonwoven Mats

---

## SECTION 2 – HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

---

Hazardous Components (Specific Chemical Identity, Common Name)	OSHA PEL	ACGIH TLV	Other Limits Recommended	% (optional)
Aramid Fiber			2 f/cc (mfg)*	

\*Manufacturer's exposure limit

---

## SECTION 3 – PHYSICAL/CHEMICAL CHARACTERISTICS

---

**BOILING POINT:** N/A

**SPECIFIC GRAVITY (H<sub>2</sub>O=1):** <1

**VAPOR PRESSURE (mm Hg.):** N/A

**MELTING POINT:** N/A

**VAPOR DENSITY (AIR=1):** N/A

**EVAPORATION RATE (BUTYL ACETATE=1):** N/A

**SOLUBILITY IN WATER:** Negligible

**APPEARANCE AND ODOR:** Yellow nonwoven mat

---

## SECTION 4 – FIRE AND EXPLOSTION HAZARD DATA

---

**FLASH POINT (METHOD USED):** N/A

**FLAMMABLE LIMITS:** N/A

**EXTINGUISHING MEDIA:** Water, CO<sub>2</sub>

**SPECIAL FIRE FIGHTING PROCEDURE:** Wear self-contained breathing apparatus

**UNUSUAL FIRE AND EXPLOSION HAZARDS:** Toxic by products may be released

---

## SECTION 5 – REACTIVITY DATA

---

**STABILITY:** Unstable  
Stable X

Conditions To Avoid – Hot poorly ventilated areas

**INCOMPATIBILITY (MATERIALS TO AVOID):** None to our knowledge

**HAZARDOUS DECOMPOSITION OR BYPRODUCTS:** Thermal decomposition may generate carbon monoxide and other toxic byproducts

**HAZARDOUS POLYMERIZATION:** Will Not Occur

---

## SECTION 6 – HEALTH HAZARD DATA

---

**ROUTE(S) OF ENTRY:**

Inhalation – Yes

Skin – Yes

Ingestion – No

**HEALTH HAZARDS (ACUTE AND CHRONIC):** Aramid fiber is a possible skin irritant

**CARCINOGENICITY:** N/A

**SIGNS AND SYMPTOMS OF EXPOSURE:** Irritation of skin

**MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE:** None to our knowledge

**EMERGENCY AND FIRST AID PROCEDURES:** Remove to fresh air. Flush eyes with water. Wash skin with soap and water.

---

## SECTION 7 – PRECAUTIONS FOR SAFE HANDLING AND USE

---

**STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:** Pick up pieces and vacuum. Use dust suppressant if sweeping is necessary.

**WASTE DISPOSAL METHOD:** Dispose of in accordance with federal, state and local regulations.

**PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING:** Store in a cool, well ventilated area.

**OTHER PRECAUTIONS:** Avoid creating dust. Avoid inhalation. Avoid excessive contact with skin.

---

## SECTION 8 – CONTROL MEASURES

---

**RESPIRATORY PROTECTION (SPECIFY TYPE):** Not normally required if adequate ventilation is provided.

**VENTILATION:** Local Exhaust – Recommended for cutting and slitting operations; and at elevated temperatures. Mechanical (General) – Recommended

**PROTECTIVE GLOVES:** Not normally required

**EYE PROTECTION:** Not normally required

**OTHER PROTECTIVE CLOTHING OR EQUIPMENT:** Not normally required

**WORK/HYGIENIC PRACTICES:** Follow usual measures of personal hygiene

---

## SECTION 9 - COMMENTS

---

The information accumulated herein is believed to be accurate but is not warranted to be, whether originating with Fibre Glast Developments Corporation or not. Recipients

are advised to confirm in advance of need that the information is current, applicable, and suitable to their circumstances.